

TOP SECRET

25 YEAR RE-REVIEW

T O P S E C R E T 192216Z

25X1 EMERG [REDACTED] 0601

25X1 [REDACTED]

25X1 REF A 0593
B 0595
C 985

EMERGENCY

25X1 REF A PARA D. AT 0523Z PILOT OBSERVED BOTH [REDACTED] WARNING
LIGHTS COME ON FOR APPROX 20 SEC, AND THEN GO OUT. THIS OCCURRED
TOTAL OF THREE TIMES OVER APPROX 2 MIN PD. WHILE LIGHTS WERE ON
PILOT HAD STROBE

ON SCOPE INDICATING POSSIBLE FRUIT SET SITE
DIRECTLY AHEAD. ALSO HAD HIGH PITCHED AUDIO SIMILAR TO FRUIT SET.
AT THIS TIME HE MADE LEFT 90 DEG TURN AND LOST INDIC. DURING
PERIOD 0630-0700Z PILOT HAD INTERMITTENT AND VERY

WEAK SYS 12

INDICATIONS SUCH THAT BARELY READABLE AND UNABLE DETERMINE BEARING.
POSSIBLY SAME SITE.

T O P S E C R E T

CFN 192216Z 0601 X 0593 0595 1985 A D 0523Z HORS 128 20 SECN 1 MIN

25X1 STROBE 90 DEG INDIC 0630-0700Z [REDACTED]